

2071

TUFF-LOK X-LINK WOOD FLOORING ADHESIVE

Performance Warranty

Taylor 2071 Tuff-Lok X-Link with Meta-Tec® technology offers a performance warranty equal to the wood flooring manufacturer's warranty. W.F. Taylor Co., Inc. warrants that 2071 Tuff-Lok X-Link Wood Flooring Adhesive is guaranteed for the installation of all parquet, engineered wood flooring, acrylic impregnated wood flooring, long-plank, and pre-finished and un-finished solid wood up to ¾" thick over approved subfloors. Exotic species of flooring such as Bamboo, Brazilian Cherry, Mahogany, and other exotic woods may behave differently than standard domestic hardwood commonly used in flooring installations.

Note: Contact W.F. Taylor for exotic species recommendations. Not recommended for Teak flooring.

This adhesive must be used in accordance with Taylor's published pre-installation and jobsite installation instructions, and the wood flooring manufacturer's subfloor, moisture and alkali limitations. Failure to follow these specific instructions completely will void the warranty

This warranty does not extend to or cover failures from conditions of high alkali, hydrostatic pressure, excessive vapor emissions, uneven subfloors beyond the manufacturer's and Taylor's specifications and tolerances; unapproved subfloor materials, improper material selection; improper substrate preparation; improper installation; or complaints relative to defects in the wood flooring materials.

This warranty does not cover damage to the adhesive or wood flooring caused by the introduction of excessive water from such causes as broken water pipes, sink overflow, leaky plumbing, flooding, weather conditions, or improper maintenance.

Being a natural product, hardwood flooring will expand and contract through normal seasonal temperature and humidity variations. Periodic separation between floorboards is a normally occurring condition and is not an adhesive related defect.

W.F. Taylor Co., Inc. reserves the right to physically inspect and determine the cause for each claim. All claims repaired and/or replaced prior to inspection will void the warranty. In the event of an adhesive bond failure judged to be so solely by an authorized Taylor representative, Taylor will repair or replace at our discretion that section of the floor judged to have failed.

This warranty is limited to one repair or replacement and in all cases is the sole remedy and obligation offered. Incidental and/or consequential damages are excluded under this warranty.

Corporate Office: 11545 Pacific Avenue, Fontana, CA 92337; 800.397.4583

Eastern Regional Office: 3601 US Highway 41 South, Dalton, GA 30721; 800.868.4583

www.wftaylor.com * info@wftaylor.com

12/01/07

MS Plus Wood Flooring Adhesive

Performance Warranty

Taylor MS Plus with Meta-Tec® technology offers a performance warranty equal to the wood flooring manufacturer's warranty.

W.F. Taylor Co., Inc. warrants that MS Plus Wood Flooring Adhesive is guaranteed for the installation of all parquet,

engineered wood flooring, acrylic impregnated wood flooring, long-plank, and pre-finished and un-finished solid wood up to

¾" thick over approved subfloors. MS Plus is also warranted for use with thin gauge solid hardwoods and exotic species of

flooring such as Bamboo, Brazilian Cherry, and Mahogany.

This adhesive must be used in accordance with Taylor's published pre-installation and jobsite installation instructions, and

the wood flooring manufacturer's subfloor, moisture and alkali limitations. Failure to follow these specific instructions completely

will void the warranty.

This warranty does not extend to or cover failures from conditions of high alkali, hydrostatic pressure, vapor emissions

above the specified limits, uneven subfloors beyond the manufacturer's and Taylor's specifications and tolerances, unapproved

subfloor materials, improper material selection, improper substrate preparation, improper installation, or complaints

relative to defects in the wood flooring materials.

This warranty does not cover damage to the adhesive or wood flooring caused by the introduction of excessive water from

such causes as broken water pipes, sink overflow, leaky plumbing, flooding, weather conditions, or improper maintenance.

Being a natural product, hardwood flooring will expand and contract through normal seasonal temperature and humidity

variations. Periodic separation between floorboards is a normally occurring condition and is not an adhesive related defect.

W.F. Taylor Co., Inc. reserves the right to physically inspect and determine the cause for each claim. All claims repaired

and/or replaced prior to inspection will void the warranty. In the event of an adhesive bond failure judged to be so solely by an

authorized Taylor representative, Taylor will repair or replace at our discretion that section of the floor judged to have failed.

This warranty is limited to one repair or replacement and in all cases is the sole remedy and obligation offered. Incidental

and/or consequential damages are excluded under this warranty.

Corporate Office: 11545 Pacific Avenue, Fontana, CA 92337; 800.397.4583

Eastern Regional Office: 3601 US Highway 41 South, Dalton, GA 30721; 800.868.4583

www.wftaylor.com * info@wftaylor.com

12/01/07